


### 1. Install USB-C Dongle

- Insert USB-C dongle into end of e285


1



### 2. Install e285 Into Sled

- Note orientation of pairing sled and insert USB-C end of e285 into sled as shown.
- Push down on opposite end of e285 to secure in place

2



### 3. Install EC50 Into Sled

- Note orientation of pairing sled and insert scanner end of EC50 into sled as shown.
- Push down on opposite end of EC50 to secure in place and fully complete the pairing sled assembly

3

